

Bushnell Turbid water 11/9/2011 Reported to PADEP Oil & Gas approximately 3:00 pm 11/10/2011

- Water initially sampled on 5/11/2011 as part of Cabot's pre-drill sampling program.
- Moody collected samples prior to the complaint for the Heitzenroder Pad on 11/9/2011
- Cabot received notice of turbid water 11/9/2011 ~ 4:45 pm
- Cabot had been blasting to prepare the tank pad for the Heitzenroder well pad
- Cabot provided 40 gallons of drinking water to the Bushnell's 11/9/2011, later in evening
- Restaurant open for business 11/10/2011 using disposable dishes
- Did a pumping test at variable flow rate, between 1 gpm up to 2.5 gpm for a period of approximately 6 hours. Well water turbidity ranged from 22ntus to start down to 3-5 ntus then stabilized in the 8-10 ntu range at end of testing, based on telephone conversation with consultant.
- Collected sample of well water post pumping test
- Installed filter on line, post filter field sample showed < 1 ntu
- Will return to evaluate and follow up on 11/11/2011

The restaurant well serves three buildings; the restaurant, the post office and Ex. 6 - Personal Privacy residence. At this time we have had no complaints from the two additional users. We will follow up with the investigation.

At this time Cabot has contact information for the Bushnell's as:

Restaurant

Bob Bushnell
3911 SR 29
Springville, PA 18844
(570) 965 2630

Home

Ex. 6 - Personal Privacy